

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 01/13/20 Time: 11:48 am Weather: Cloudy 43°F

General Site Conditions

Site was in good condition. Lower geotubes significantly exposed along structure.

Type & Quantity of Debris Removed/Action Taken

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

Collected several bricks. ~ 1 gallon.



2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 01/14/20 Time: 12:32am Weather: Cloudy 42°F

General Site Conditions

Site was in good condition. Lower geotubes partially exposed along no structure.

Type & Quantity of Debris Removed/Action Taken

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

Collected several bricks. ~ 1 gallon.



2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 01/15/20 Time: 12:32am Weather: Sunny 44°F

General Site Conditions

Site was in good condition. Lower geotubes partially exposed along no structure.

Length Of Exposed Geotube:

~ 340 feet.



Type & Quantity of Debris Removed/Action Taken

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris were collected during inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 01/16/20 Time: 12:32pm Weather: Sunny 44°F

General Site Conditions

Site was in good condition. Lower geotubes partially exposed along no structure.

Length Of Exposed Geotube:

~ 340 feet. No changes



Type & Quantity of Debris Removed/Action Taken

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris were collected during inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 01/17/20 Time: 8:48am Weather: Cloudy 34°F

General Site Conditions

Site was in good condition. Lower geotubes partially exposed along no structure.

Length Of Exposed Geotube:

372 feet exposed.



Type & Quantity of Debris Removed/Action Taken

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris were collected during inspection.