

Rec. @ meeting
from Dirk + Sharon
VanLieu (4/30/14)



Taken 12/15/2013
showing erosion
from runoff in the
area now covered
by geotubes.



Taken 04/08/2014



Taken 02/08/2014
after geotube
installation was
completed.



Taken 04/26/2014
showing considerable
erosion



Taken 04/08/2014
on the lot adjacent to 87
Baxter Road to the north
showing runoff from the
top of the Bluff.



Taken 04/08/2014
on top of the geotubes
showing runoff from
the top.